

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

> JOHN R. BAZA Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
OGM	Karl Houskeeper Environmental Scientist III					
Other	Dana Shepherd Field Technician/Draftsman					

Inspection Report

Permit Number:	C0150032 PARTIAL			
Inspection Type:				
Inspection Date:	Wednesday, January 03, 2007			
Start Date/Time:	1/3/2007 9:30:00 AM			
End Date/Time:	1/3/2007 12:00:00 PM			
Last Inspection:	Thursday, December 07, 2006			

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy, Temp. 38 Deg. F.

InspectionID Report Number: 1180

Accepted by: pgruba

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC Site: CRANDALL CANYON MINE

Address: PO BOX 1077, PRICE UT 84501

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

6,235.80	Total Permitted			
10.70	Total Disturbed			
	Phase I			
	Phase II			
	Phase III			

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State Surface County ☐ Loadout Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

A midterm review of the Crandall Canyon Mine Permit C/015/0032 is currently in progress.

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date

Wednesday, January 03, 2007

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 03, 2007

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
- a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches	V	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓	✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 03, 2007

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

A midterm review of the Crandall Canyon Mine Permit C/015/0032 is currently in progress.

2. Signs and Markers

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator. All other signs and markers observed during the inspection met the coal rules.

4.a Hydrologic Balance: Diversions

The diversion adjacent to the retaining wall by the mine substation has snow pushed into the diversion. The snow needs to be removed from the diversion. The snow was being removed during the inspection.

The drop inlet structures by the road entrance and adjacent to the crusher building are functional, but need maintenance to prevent them from plugging.

4.d Hydrologic Balance: Water Monitoring

Third quarter 2006 water monitoring is in the EDI website and is uploaded. Water monitoring is current.

18. Support Facilities, Utility Installations

An oil spill was observed in the oil storage building. The oil spill needs to be cleaned up.